


PLATE 2

SECTION ALONG HOLE 8



winze drift from cap of hole 8