

FIGURE-12- ARRANGEMENT OF PRIMARY DRILL HOLE IN BANK - MORENCI MINE