
Fault zone
Line 2
Line 1
Line 3
Shallow bedrock
Heavy overburden
Picacho Mountains
Newman Peak
Airway Beacon
Gold Bell Mine
BM 1892
Clemens
Bogard Wash
Durham Wash
Barnett Well
LANDING FIELD
Well
McClellan Wash
Wymola
Mormon Trail Historical Marker
BM 1775
PIPELINE
BM 1794
Pass
Picacho Peak
BM 1797
Picacho Pass
Landing Strip
JEEP TRAIL
R. 9 E.
R. 10 E.