SKIP DUMP

11th LEVEL

2 - 650 TON

ORE CHUTES

12th LEVEL

approx 33'-0"

ORE CHUTE FROM 12th LEVEL

Silica Ore Chute

2 - 1000 TON

ORE POCKETS

1st Class Ore

2nd Class Ore

Silica Ore

L - 350 Ton Pocket

CHUTES TO ORE CARS.

13th LEVEL

TUNNEL

Extension of 12th Level Station Drift. See drg. No. 3210M for Plan & Location

LOADING DIAGRAM

1st Position Empty Car Filling

Normal Position Filling Car

2nd Position Empty Car Filling

3rd Position Empty Car Filling

PROJECTION LOOKING SOUTH.

PROJECTION

LOOKING WEST.

AUDREY SHAFT

GENERAL ARRANGEMENT OF LOADING POCKETS AT SHAFT.

THE UNITED VERDE EXT. MINING CO.

JEROME, ARIZ.

Scale 1/8" = 1 Foot. Date Aug. 1917

Drawn by A. Traced by A. Checked by

Approved by By

E-4