CONTACT INFORMATION
Mining Records Curator
Arizona Geological Survey
3550 N. Central Ave, 2nd floor
Phoenix, AZ, 85012
602-771-1601
http://www.azgs.az.gov
inquiries@azgs.az.gov

The following file is part of the Grover Heinrichs Mining Collection

ACCESS STATEMENT

These digitized collections are accessible for purposes of education and research. We have indicated what we know about copyright and rights of privacy, publicity, or trademark. Due to the nature of archival collections, we are not always able to identify this information. We are eager to hear from any rights owners, so that we may obtain accurate information. Upon request, we will remove material from public view while we address a rights issue.

CONSTRAINTS STATEMENT

The Arizona Geological Survey does not claim to control all rights for all materials in its collection. These rights include, but are not limited to: copyright, privacy rights, and cultural protection rights. The User hereby assumes all responsibility for obtaining any rights to use the material in excess of "fair use."

The Survey makes no intellectual property claims to the products created by individual authors in the manuscript collections, except when the author deeded those rights to the Survey or when those authors were employed by the State of Arizona and created intellectual products as a function of their official duties. The Survey does maintain property rights to the physical and digital representations of the works.

QUALITY STATEMENT

The Arizona Geological Survey is not responsible for the accuracy of the records, information, or opinions that may be contained in the files. The Survey collects, catalogs, and archives data on mineral properties regardless of its views of the veracity or accuracy of those data.

NOTES ON RECENT EVENTS AT PRODUCERS MINERALS CORPORATION PEACOCK MINE, GRAHAM COUNTY, ARIZONA

July 28, 1972

Conversation with employees Raymond Rhodes, Vance Jenner, Howard Campbell, at Peacock Mine:

1) No crushing for 13 months; peaked at average production of 9 TPD copper with a few days at 13 TPD and one day at 16 T.

2) Recent production of 20 tons copper every two weeks.

3) Employees literally have nothing to do, they shoot craps, play cards, whatever, to pass the time.

4) Ribble Equipment Co. in Albuquerque, will pick up crushing equipment next week unless Moulds pays up; he is 90 days in arrears.

July 31, 1972

Hourly workers at Peacock Mine were paid last Friday but checks all bounced. They returned to work Monday and 14 men were fired, leaving only four as watchmen.

August 1, 1972

No pumps are operating at Peacock Mine. Raw acid is being dumped in low grade run-of-the-mine material above the fine leach dumps and allowed to percolate down through fine leach dumps.

August 2, 1972

John Boss, watchman at Peacock Mine, says they will lose 100 to 200 pounds of copper per day due to seepage.

Three acid trucks dumped between 8 a.m. and 10 a.m..

Representative for Ribble Equipment Co. arrived at mine at 10 a.m.

August 3, 1972

Ribble is removing crushing equipment.

August 8, 1972

Conversation with Sam Short of N.C. Ribble Co. They have removed 4 conveyors, 2 cone crushers and are working on primary crusher. This equipment was all purchased by Producers. Some other crushing equipment is rented and may go later.

August 9, 1972

Conversations with Grant Godfrey and Sam Short. Grant says John Boss, Ron Gietz, and Chuck Lambert are other watchmen and secretary has quit. Trucks are dumping 100-200 TPD of acid.

Sam Short says all equipment will be removed today and is going to Albuquerque. Western Machiner Co. of Phoenix repossessed their Gardner-Denver track drill and compressor this morning.

August 19, 1972

Spent day counting acid trucks at Peacock Mine. (Memo submitted). John Farris has replaced Chuck Lambert as watchman.

Augsut 21, 1972

Spent day counting acid trucks at Peacock Mine. (Memo submitted.)

August 23, 1972

Two acid trucks arrived Peacock Mine at 8:30 a.m. and two more at 10:20 a.m.

August 29, 1972

Two acid trucks at Peacock Mine at 5 p.m.

September 5, 1972

Combination of acid and rain is eroding road behind the shop at Peacock Mine. Also first earth fill dam up the same wash with the caterpillar pump on it has started to erode. One more good vain will take them both.

September 8, 1972

Acid truck at Peacock Mine at 7:30 a.m. One load of scrap iron was hauled in but so far is not in the launder cells. Petit and Williams have been hired back temporarily. They have started caterpillar pump on lowest collecting pond. Ribble has removed two more conveyors.

September 11, 1972

San Juan pumps are running and acid is being pumped on to main leach dump. Load of scrap iron is in the launders.

September 12, 1972

One acid truck at Peacock Mine at 2 p.m. Pumping has markedly reduced acid level in the two lower ponds. Road behind shop is repaired.

September 13, 1972

Two acid trucks at Peacock Mine at 9 a.m.

September 15, 1972

Conversed with Francis Pettit and Grant Godfrey. Producers is two weeks behind on paychecks. They are circulating acid through launders to retrieve 2 loads of copper they believe is in solution. One acid truck at 11 a.m.

September 20, 1972

Two acid trucks at 2 p.m. Another load of scrap iron is in launder and a small load of cement copper is on drying pad.

September 24, 1972

Conversed with John Farris. One load of copper is gone and another is still in launder. Mr. Farris estimates they are making two tons of copper per day.

All caterpillar equipment has been repossessed and removed by finance company (rumored to be Thorpe Finance Co.) and reportedly will be put up for auction. With no loader available Producers cannot move their copper.

October 5, 1972

All pumps have been shut down within the last three days and the two temporary employees, Williams and Pettit, no longer are working.

October 6, 1972

One acid truck at 2:30 p.m.

October 8, 1972

Conversation with John Boss at Peacock Mine.

1) Sheriff was out to inspect the premises but no one knows why.

2) Electricity has been shut off.

October 8, 1972 - continued

3) Hydrocarbon contaminants are no longer skimmed off the acid before dumping. The ultimate result will be coating of particles and plugging of pores in the leach dump.

4) Board of Health representatives inspected premises. They would be inclined to overlook problems if the mine had a normal payroll and were in actual production. They did voice objection to just dumping acid on the property.

5) Acid concentration. They believe 12 grams/liter is probably optimum. Occasionally they receive orders from El Paso (?) to run as high as 24 grams/liter. Approximately five pounds of acid will make one pound of copper.

October 13, 1972

Conversed with Grant Godfrey. A total of 291 loads of acid has been dumped on the fine leach pile since the pumps were turned off about July 31, 1972. There is a rumor that Standard Oil is now paying the salaries of those still employed at the Peacock Mine.

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running?
2) Is acid being distributed on main leach dump?
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap?
4) Where are the acid trucks dumping?
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? In collection trough below cells?
7) Is there scrap iron in the cells?
8) Has any scrap iron been added to cells since previous inspection?
9) Is there any new scrap iron on the ground?
10) List date, time, and license number of acid trucks on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer_____ Date_____

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - both
2) Is acid being distributed on main leach dump? yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? ~~top~~ of fine leach dump
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? small pile
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? yes
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

3 PM Tractor R-3584 Trailer Y15-178 } Texas

3:30 PM Tractor R-3583 Trailer Y12-806

11) Describe any changes in routine or unusual activity on the property.

The Sheriff had been out to attach one of the trailer offices, license Az YT-8560 (1972), and it will be removed tomorrow. John Boss did not know who it was going to.

Also the water truck had been moved from the crusher down to the office area.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-15-73

3 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? only one
2) Is acid being distributed on main leach dump? yes
   If so, which side? west
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place - fine leach heap
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? only some small pile
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.
2:15 PM tractor R-3584 trailer 415-178

11) Describe any changes in routine or unusual occurrences on the property.
All acid is being pumped onto west side of main leach heap. None is being pumped through the cut line onto main leach heap or onto fine leach heap

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-16-73
2 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - both
2) Is acid being distributed on main leach dump? yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? some place - fine leach heap
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? some small pile
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? adding while observer was present
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.
    3:15 PM Tractor R-3584 Trailer Y15-178

11) Describe any changes in routine or unusual activity on the property.
    Acid again spewing from cut line north side of steady head tank

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-17-73
3 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes
2) Is acid being distributed on main leach dump? yes
   If so, which side? west and center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trunks dumping? fine leach heap
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? small pile
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection?
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

Some acid had been dumped over edge of embankment 150' north of steady head tank. Truck broke the 4 inch acid line by backing over it.

On the diagram indicate the location of scrap iron and cement copper.



Observer Tony Corse Date 3-19-73
10 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? Yes
2) Is acid being distributed on main leach dump? Yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? Yes
4) Where are the acid trucks dumping? Yes
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? No
   In collection trough below cells? Yes
7) Is there scrap iron in the cells? Yes
8) Has any scrap iron been added to cells since previous inspection? No
9) Is there any new scrap iron on the ground? No
10) List date, time and license number of acid trucks seen on or near the property.
    3-20-73, 9:15, J 11-336 (Tex), ← tractor trailer, Chemical Producers.
11) Describe any changes in routine or unusual activity on the property.
    As noted in yesterdays report, acid is still leaking from broken transfer pipe.

On the diagram indicate the location of scrap iron and cement copper.



Observer Nixon A. Jaroja Date 3-20-73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) **Is the circulation pump running?** yes - both
2) **Is acid being distributed on main leach dump?** yes
   If so, which side? east
3) **Is acid being pumped onto run-of-the-mine rock and fine leach dump?** yes
4) **Where are the acid trucks dumping?** slightly further north on run of the mine rock
5) **Is acid circulating through exchange cells?** yes
6) **Is there cement copper on drying pad?** some small pile
   In collection trough below cells? yes
7) **Is there scrap iron in the cells?** yes
8) **Has any scrap iron been added to cells since previous inspection?** no
9) **Is there any new scrap iron on the ground?** no
10) **List date, time and license number of acid trucks seen on or near the property.**
    3:30 PM tractor (Ryder rental) J11-336
    trailer 412-807
11) **Describe any changes in routine or unusual activity on the property.**
    Cherry water truck C-50 may be gone?
    Yes, it is. 3-24-73

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-21-73
3:30 PM.

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? Yes
2) Is acid being distributed on main leach dump? Yes
   If so, which side? CENTER
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? Yes
4) Where are the acid trucks dumping? FINES
5) Is acid circulating through exchange cells? YES
6) Is there cement copper on drying pad? YES
   In collection trough below cells? YES
7) Is there scrap iron in the cells? YES
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? NO
10) List date, time and license number of acid trucks seen on or near the property. NONE

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Nelson N. Jones Date 3-29-73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? YES - ONE
2) Is acid being distributed on main leach dump? YES
   If so, which side? LEFT → CENTER
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? YES
4) Where are the acid trucks dumping? FINES
5) Is acid circulating through exchange cells? YES - VERY LOW LEVEL IN CELLS 6–13
6) Is there cement copper on drying pad? YES
   In collection trough below cells? NO
7) Is there scrap iron in the cells? YES
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? YES
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer _____ Date 3/23/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - both
2) Is acid being distributed on main leach dump? yes
   If so, which side? east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trunks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes - an entire new layer
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-24-73
4 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? Yes
2) Is acid being distributed on main leach dump? Yes
   If so, which side? Center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? Yes
4) Where are the acid trucks dumping? SAME
5) Is acid circulating through exchange cells? NO
6) Is there cement copper on drying pad? NO
   In collection trough below cells? YES
7) Is there scrap iron in the cells? YES
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? NO
10) List date, time and license number of acid trucks seen on or near the property.
    3-26-73, 2 PM, ARIZ 3TD-633 → used for hauling copper cement, Cecil Trucking Inc.
11) Describe any changes in routine or unusual activity on the property. Exchange cells 6, 7, and 8 were washed with water to remove copper cement, the copper cement and water were in the collection trough. A front loader was used to move the dry copper cement from the drying pad into the truck described above.

On the diagram indicate the location of scrap iron and cement copper.



Observer Wayne A. Longa Date 3-26-73

Information obtained on 3-29-73 indicates a load of copper was shipped out today in the PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - both
2) Is acid being distributed on main leach dump? yes
   If so, which side? east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trunks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes -
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? yes #8 cell
9) Is there any new scrap iron on the ground? no - very little remaining
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.
John Boss & Ron Gietz were trying to operate high pressure water pump to wash out cells 6 & 7.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-27-73
9 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? no - only small pile
   In collection trough below cells? no
7) Is there scrap iron in the cells? a little in #6,7; new heap #8
8) Has any scrap iron been added to cells since previous inspection? yes - some to #8
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.
    R-3584 tractor } 5:45 PM
    trailer Y15-178 }
11) Describe any changes in routine or unusual activity on the property.
    All copper has been removed from drying pad except small pile in corner. Small pile now consists of remnants of two loads removed from drying pad. A load must have gone out late Tues or Wed.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-29-73
5:45 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? only a little
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? small copper
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes #8
8) Has any scrap iron been added to cells since previous inspection? yes #8
9) Is there any new scrap iron on the ground? no - it is all gone
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3-29-73 4 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? no
2) Is acid being distributed on main leach dump? no
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? Some place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes - small pile; see comments below
   In collection trough below cells? no - in process of being cleaned out
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? yes - to # 8
9) Is there any new scrap iron on the ground? no - it is all gone
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.
    See comments at bottom of page

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4-2-73
3 PM

George Herman of Assoc. Concrete Products had just loaded a truck with copper (Cecil Trucking of Globe) and was cleaning out the sump. He said PMC had contracted for $1,200 worth of loader work in March which was higher than usual. PMC must pay their bill twice monthly or Assoc. Concr. Prod. will no longer do their work. He further stated that all trucks going to Ely were overweight, up to 28-30 tons

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes - small amount
4) Where are the acid trucks dumping? Don't know for sure.
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes #8
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

1) Normally two diesel motors operate the main circulation pumps, a Detroit and a Cummins. Today the Cummins diesel is missing from its mounting and could not be located on the property.

(continued below)

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4-4-73
1:15 PM

2) The compressor used to unload the acid trucks has been moved onto the drying pad. Employees are using a jack hammer, picks, and shovels to remove a layer of compacted cement copper adhering ~~the~~ the surface of the concrete. This layer varies from ½" to 3" thick and is thickest at the north end of the collecting sump.

3) ~~Reuben~~ Jack Jackson 4/5/73 ~~Meeds~~ was at the property but no contact was made. Jackson works for CPC in El Paso.

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump?
   If so, which side? yes - east + center
3) Is acid being pumped onto run-of-the-mine rock
   and fine leach dump? yes
4) Where are the acid trucks dumping? into storage tanks on east side
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes #8
8) Has any scrap iron been added to cells since
   previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks
    seen on or near the property.
    R-3583 tractor 11 AM leaving property
    Y 12-806 trailer

11) Describe any changes in routine or unusual
    activity on the property.
    Small compressor used to unload acid trucks into storage tanks.
    Large compressor being used to help scale off drying pad.

    #4 cell washed out this morning and possibly others.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4-5-73
11-12:30 AM

Visited property with Lyle Likty.
Dave Williams said Cummins diesel was taken to El Paso for overhaul.

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? If so, which side? yes - east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place on top run-of-mine-rock + fine leach heap
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes - what they have scaled off pad plus pile in corner
   In collection trough below cells?
7) Is there scrap iron in the cells? yes a few
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.
large compressor for unloading acid trucks replaced in original location at top of run-of-mine and fine-leach heap

On the diagram indicate the location of scrap iron and cement copper.



Observer B. L Helming Date 4/6/73
11 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? If so, which side? yes - east side
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? some place, onto run-of-mine heap
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes In collection trough below cells? yes
7) Is there scrap iron in the cells? yes #8
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.
washing out cell #4
Dave Williams said a load of copper was shipped yesterday, Sunday April 8. He also confirmed that PMC had been working unusually hard the last 2 or 3 weeks to produce copper.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 9:45AM 4/9/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? no
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes #8
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? yes
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.
Load of scrap iron received Tuesday afternoon.
Crew is washing out all cells not currently in use.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/12/73
2 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes one
2) Is acid being distributed on main leach dump?
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock
   and fine leach dump? yes
4) Where are the acid trucks dumping? some place
5) Is acid circulating through exchange cells? only one on north end
6) Is there cement copper on drying pad? yes
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes # 8
8) Has any scrap iron been added to cells since
   previous inspection?
9) Is there any new scrap iron on the ground?
10) List date, time and license number of acid trucks
    seen on or near the property.
    truck leaving 10:30 AM

11) Describe any changes in routine or unusual
    activity on the property.
Only 1 cell on the north end contains any acid. All other cells are empty of acid and being washed out

On the diagram indicate the location of scrap iron and cement copper.



Observer Bill Brown Date 10:30 AM 4/13/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running?
2) Is acid being distributed on main leach dump?
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock
   and fine leach dump?
4) Where are the acid trucks dumping?
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad?
   In collection trough below cells?
7) Is there scrap iron in the cells?
8) Has any scrap iron been added to cells since
   previous inspection?
9) Is there any new scrap iron on the ground?
10) List date, time and license number of acid trucks
    seen on or near the property.

11) Describe any changes in routine or unusual
    activity on the property.

Did not visit property on this date but a conversation with George Herman of Assoc. Concrete Products on Wed. April 18 revealed that a load of cement copper left the property on this day Sunday April 15.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/15/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? no - impeller shaft on pump is broken
2) Is acid being distributed on main leach dump? no
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes - reduced flow
6) Is there cement copper on drying pad? yes
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes 7 & 8
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? y
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

It appears the collecting trough may have been cleaned out over the weekend.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 1 PM 4/16/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes
2) Is acid being distributed on main leach dump? center
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes 7+8
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.
Bill Brown reported acid trucks at 10 AM and 2:45 PM

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/17/73
10 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? very little
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes 6-7-8-9
8) Has any scrap iron been added to cells since previous inspection? yes #9
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

Truckload of copper just leaving the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3PM 4/18/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes
2) Is acid being distributed on main leach dump? yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? Same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? very little
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes 6-7-8-9
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.
truck approaching property at 3:30 PM
tractor R-3584
11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 3:30 PM 4/19/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes - very little
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? no
6) Is there cement copper on drying pad? very little
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes 6-7-9
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

They were cleaning cell # 8, all scrap iron had been moved to # 9.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 1:45 PM 4/20/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? very little
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes - 6-7-8-9
8) Has any scrap iron been added to cells since previous inspection? yes 8 + 9
9) Is there any new scrap iron on the ground? No - stockpile is gone
10) List date, time and license number of acid trucks seen on or near the property.
Acid truck at 3 PM.

11) Describe any changes in routine or unusual activity on the property.
cells 3-4-5 are dry
John and mechanic were working on cat pump on pond below main circulation pump.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/23/73

Bill + Bert observed two men collecting samples in the pit area in the afternoon. They were later identified as Humble geologists. Correction They said they worked for CMC in El Paso.

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes — one
2) Is acid being distributed on main leach dump? yes
   If so, which side? east
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? some place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes — very little
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes 7-8-9
8) Has any scrap iron been added to cells since previous inspection? no.
9) Is there any new scrap iron on the ground? no.
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/25/73
10 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? center
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? very little
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes 7-8-9
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.
    8:50 AM
    tractor R-3584

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/26/73
8:45 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? If so, which side? —
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes - a little In collection trough below cells? yes
7) Is there scrap iron in the cells? yes 7-8-9
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Date 4/27/73
10 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? If so, which side? —
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? No
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? yes
   In collection trough below cells? yes a little
7) Is there scrap iron in the cells?
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? yes
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Date 4/28/73

Conversation between Joe and Ron Gietz:

Gietz said Ass. Concr. Products was bring out two trucks, loader, and bulldozer to move the broken ore in bottom of pit. He also said PMC was going to do some more blasting in the pit and without crushing it, haul it onto the leach heap and start running acid over it.

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? east side
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes 7-8-9
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? yes - arrived 4-29-73
10) List date, time and license number of acid trucks seen on or near the property.
    tractor R-3584 arrived 9:20 AM

11) Describe any changes in routine or unusual activity on the property.
HD-16 bull dozer on property has cleared a road across the run-of-the-mine rock above fine leach heap where they were dumping acid until one month ago. (see photo)

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 4/30/73

9 AM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? on the west side
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? no
4) Where are the acid trucks dumping? see below
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? yes
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? yes
9) Is there any new scrap iron on the ground? no
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

dumping acid E end of steady head tank off Edge of new road

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr. Date 5/1/73

Guy Anderson plus 2 men and 1 woman were on their way to mine. John Bass said some big shots from Dallas were expected today.

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? no
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the ground? NO
10) List date, time and license number of acid trucks seen on or near the property.
    acid truck 2:45 PM
    tractor R-3586
11) Describe any changes in routine or unusual activity on the property. NO

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Madrigal Date 5/2/

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? NO
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? yes
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? NO
10) List date, time and license number of acid trucks seen on or near the property.

Tractor - R-3584 - arrived 9:25 AM

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr Date 5/3/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? all over
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes - in area previously used for dumping trucks
4) Where are the acid trunks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? a little
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes 6-7-8-9 full
8) Has any scrap iron been added to cells since previous inspection? yes
9) Is there any new scrap iron on the ground? No
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date 5/4/73
1 PM

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? all over
3) Is acid being pumped onto run-of-the-mine rock
   and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes little
   In collection trough below cells? yes
7) Is there scrap iron in the cells? yes - 6-7-8-9-fair
8) Has any scrap iron been added to cells since
   previous inspection? NO
9) Is there any new scrap iron on the ground? NO
10) List date, time and license number of acid trucks
    seen on or near the property.

11) Describe any changes in routine or unusual
    activity on the property.

Elpaso called and wanted copper

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr Date 5/5/73

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - ONE
2) Is acid being distributed on main leach dump?
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap? ALL - PADS
4) Where are the acid trucks dumping? SAME - Place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? NO
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? NO
10) List date, time, and license number of acid trucks on or near the property.

11) Describe any changes in routine or unusual activity on the property.

Acid RUNNING ON ALL PADS BUT VERY LOW.
CELLS CLEAN & COPPER STILL IN SUMP.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr. Date 5/2/23

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes. Two
2) Is acid being distributed on main leach dump? yes
   If so, which side? ~~east~~ [illegible]
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? NO
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? yes
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

Two pads running on the East side. And they are still cleaning copper. They also got a new load of scrap.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Mauldy Date 5/8/73

PRODUCERS MINERALS CORP.

PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - one
2) Is acid being distributed on main leach dump? yes
   If so, which side? IN ALL
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump?
4) Where are the acid trucks dumping? SAME - PLACE
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? NO
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? yes
10) List date, time and license number of acid trucks seen on or near the property.

R-3584 - 3:05 PM

11) Describe any changes in routine or unusual activity on the property.

SEEN Loader ON The Road up To The MINE

also SEEN Mitchell up at The Mine.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Date 5/9/73

PRODUCERS MINERALS CORP.

PLACOSAN E

Safford, Arizona

1) Is the circulation pump running? yes-one
2) Is acid being distributed on main leach dump? NO
   If so, which side?
3) Is acid being pumped onto run-of-the-mine rock and fine leach dump? NO
4) Where are the acid trucks dumping? SAME Place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? yes
9) Is there any new scrap iron on the ground? NO
10) List date, time and license number of acid trucks seen on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr. Date 5/11/73

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? NO
2) Is acid being distributed on main leach dump? NO
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap? NO
4) Where are the acid trucks dumping? SAME - PLACE
5) Is acid circulating through exchange cells? YES
6) Is there cement copper on drying pad? yes
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? yes
9) Is there any new scrap iron on the ground? yes
10) List date, time, and license number of acid trucks on or near the property.

TIME - 8:45 AM - DATE - 5/12/73 - LICENSE - NUMBER - R-3586
TIME - 9:30 AM - DATE - 5/12/73 - LICENSE - NUMBER - R3584

8 PM in Safford
R-3586

11) Describe any changes in routine or unusual activity on the property.

MR. MICTHELL was up at The MINE Saturday.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr. Date 5/12/73

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? NO
2) Is acid being distributed on main leach dump? NO
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap? NO
4) Where are the acid trucks dumping? SAME Place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells?
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? yes
10) List date, time, and license number of acid trucks on or near the property.

TIME - 8.30 PM - DATE - 5/14/73 - license NUMBER - R-3538

11) Describe any changes in routine or unusual activity on the property.

MR. BOSS STOP ME This MORNING AND SAID THAT MR. MICTHELL Told HIM That HE didn't WANT To SEE ME AROUND The SAN JUAN MINE ANY MORE THAT WE didn't HAVE The Right To be AROUND Them.
AND Mr. MICTHELL Was up at The MINE Today.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Morales Jr Date 5/14/73

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? no - there is only 1 diesel motor
2) Is acid being distributed on main leach dump? no and the pump is B/O
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap? no
4) Where are the acid trucks dumping? same place as last observed 5/14/73
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes - estimated 40 tons
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? —
9) Is there any new scrap iron on the ground? —
10) List date, time, and license number of acid trucks on or near the property.
    11:30 AM tractor R-3583
    " R-3584
11) Describe any changes in routine or unusual activity on the property.
    office trailer #3 has been removed from property

On the diagram indicate the location of scrap iron and cement copper.



Observer Helming - Morales Date June 20, 1973
11:30 AM

PROSPECTORS MINERALS CORP.
BLACKOCK MINE

Safford, Arizona

1) Is the circulation pump running? no
2) Is acid being distributed over cells each day? no
3) Is acid being pumped onto run-of-mine rock and fine leach heap? no
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? a little
6) Is there cement copper on drying pad? yes
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the property? no
10) List date, time, and license number of acid trucks on or near the property.
    tractor R-3584 3 PM
    " R-3583 4:30 PM (sampled for acid)
11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Morales Date June 21, 1973

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? no
2) Is acid being distributed on [illegible] leach dump? no
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap? no
4) Where are the acid trucks dumping? some place
5) Is acid circulating through exchange cells? a little
6) Is there cement copper on drying pad? yes
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the property? no
10) List date, time, and license number of acid trucks on or near the property.
9:30 AM tractor R-3583
R-3584
11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming Date June 22, 1973
9:15 AM

PRODUCERS MINERALS CORP
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? NO
2) Is acid being distributed on main leach dump? NO
3) Is acid being pumped onto run-of-the-mine rock and fine leach heap? NO NO
4) Where are the acid trucks dumping? SAME PLACE
5) Is acid circulating through exchange cells?
6) Is there cement copper on drying pad? YES
   In collection trough below cells?
7) Is there scrap iron in the cells? YES
8) Has any scrap iron been added to cells since previous inspection? NO
9) Is there any new scrap iron on the ground? NO
10) List date, time, and license number of acid trucks on or near the property.

11) Describe any changes in routine or unusual activity on the property.

On the diagram indicate the location of scrap iron and cement copper.



Observer Joe Montoya Date 6-25-73

PRODUCERS MINERALS CORP.
PEACOCK MINE

Safford, Arizona

1) Is the circulation pump running? yes - started this morning
2) Is acid being distributed on each dump? yes - west side
3) Is acid being pumped onto run-of-mine and fine leach heap? yes
4) Where are the acid trucks dumping? same place
5) Is acid circulating through exchange cells? yes
6) Is there cement copper on drying pad? yes
   In collection trough below cells? no
7) Is there scrap iron in the cells? yes
8) Has any scrap iron been added to cells since previous inspection? no
9) Is there any new scrap iron on the property? no
10) List date, time, and license number of all trucks on or near the property.

11) Describe any changes in routine or abnormal activity on the property.

Apparently circulation pump was started this morning. They are sprinkling acid on west side of main leach heap and also run-of-mine rock in NE corner. Also one line without sprinklers is pouring a high volume of acid onto back side of main leach heap in the northwest corner. At no point is water being added to system. (see large photo) Water line is turned off due to leak near circulation pump.

On the diagram indicate the location of scrap iron and cement copper.



Observer Bob Helming June 28, 1973
9 AM

Also feeder line from base of fine-leach heap to pump is broken so that acid spills into pond thence to pump rather than directly to pump

* conversation w/ employee confirmed that 1 load of copper was shipped Sunday, June 24, 1973