



MCF

75  
 94  
 80  
 92  
 92  
 79  
 63  
 53  
 58  
~~53~~  
 48  
 40  
 42  
 46  
 48  
 36  
 33  
 38  
 35  
 52  
 27  
 30  
 34  
 31  
 35  
 39  
 33  
 38  
 36  
 32  
 25  
 31  
 62  
 33  
~~33~~

10.1  
 12.1  
 9.7  
 12.4  
 12.9  
 7.3  
 11.9  
 9.5  
 9.0  
 7.3  
 5.1  
 5.9  
 4.9  
 3.3  
 5.1  
 3.7  
 5.2  
 3.1  
 4.2  
 3.5  
 2.7  
 3.5  
 3.0  
 3.4  
 3.6  
 4.0  
 4.4  
 4.6  
 4.2  
 4.2  
 3.6  
 3.4  
 2.8  
 3.8  
 3.4  
 2.8  
 3.8  
 3.9  
 5.1

26.7  
 12.7  
 7.4  
 4.9  
 3.4  
 3.6  
 4.2  
 4.1  
 5.1  
 5.3  
 5.9  
 5.7  
 6.5  
 4.6  
 5.2  
 3.9  
 4.1  
 6.6  
 6.6  
 5.4  
 3.5

11.4	12.6	18.1	18.4	13.0	6.2
14.2	15.6	26.3	22.4	19.7	10.4
13.6	13.7	20.0	24.8	20.3	3.4
10.2	14.4	15.1	16.4	20.0	7.2
15.8	20.8	19.8	10.5	26.5	
18.1	24.6	23.3	8.8	21.0	
12.7	15.0	17.2	21.5	12.6	
15.3	14.9	15.2	4.6	3.6	
8.7	14.6	13.6	9.6	7.9	15.6
13.7	14.4				
13.1	5.5	7.6	7.0	9.0	6.7
5.6	4.3	4.8	4.0	4.5	6.4
5.5	6.3	4.9	3.9	4.1	4.8
6.8	4.6	5.3	3.9	4.4	5.1
4.6	4.6	5.2	4.1	2.9	3.8
4.9	4.4	4.3	3.7	3.3	4.7

GRADIENT ARRAY LOCATION PLAN  
 (SCHEMATIC)  
 METALLIC CONDUCTION FACTOR  
 of  
 CUPRITE AREA  
 PIMA COUNTY, ARIZONA  
 for  
 NORTH AMERICAN MINES  
 by  
 HEINRICH'S GEOEXPLORATION COMPANY

SCALE: 1" = 500'      AUGUST 1971