



LEGEND

- ☒ Top of Raise (Rs.) or Winze (Wz).
- ☑ Bottom of Raise or Winze.
- ▬ Winze with ladder.
- ▬ Raise with ladder.
- ⋯ Stope Outline.
- 3-3 Underground Survey Station, (Level and station and Number.)
- 3-2+ Surface Survey Station and Number.
- Ch. Ore Chute.
- CS Coleman Samples - footage & Silver content.
- SB Starbird Samples - Silver content only.

COLEMAN EXPLORATION & MINING CO.
 COLUMBIA - SILVER BELL MINE
SAMPLE-ASSAY MAP
 5th LEVEL (3040)
 Pioneer Mining District
 Pinal County, Arizona
 SCALE: 1" = 30 FT.
 0 10 20 30 40 50
 JAN, 1980 R. E. MIERITZ