



IN CASE OF FIRE OR EXPLOSION

MINERS

1. PUT ON SELF RESCUE UNIT.
2. NOTIFY HOISTMEN OF LOCATION OF FIRE AS SOON AS DISCOVERED.
3. IF FIRE IS IN THE SHAFT (POINTS 1, 2 OR 3) EXIT THRU STOPE S
4. IF FIRE IS IN THE SHAFT (POINTS 4, 5 OR 6) EXIT THRU SHAFT.
5. ALL STATIONS ARE PRIMARY COLLECTION POINTS.

HOISTMEN

IN CASE OF FIRE IN (POINTS 1, 2 OR 3) THE HOISTMEN IS TO:

1. TURN OFF POWER.
2. PUT STENCH IN COMPRESSED AIR SYSTEM.
3. HAVE SOMEONE REVERSE FAN - C.
4. TURN ON SHAFT SPRINKLERS.
5. PUT FIRE HOSE DOWN SHAFT.
6. NOTIFY MINE SUPERINTENDENT.

IN CASE OF FIRE IN (POINTS 4, 5 OR 6)

1. PUT STENCH IN COMPRESSED AIR SYSTEM
2. NOTIFY MINE SUPERINTENDENT.

EN CASO DE LUMBRE OH ESPLOSION

MINEROS

1. PONGANSE LA SELF RESCUE (LA MASCARA PARA EL HUMO).
2. AVISANLE AL MALACATEO EN DONDE ESTA LA LUMBRE TAN PRONTO QUE LA DESCUBRAN.
3. SI LA LUMBRE ESTA EN EL TIRO (EN PUNTOS 1, 2 OR 3) SALGANSE POR LOS ESTOPESES.
4. SI LA LUMBRE ESTA EN LOS ESTOPESES (PUNTOS 4 OR 5) SALGANSE POR EL TIRO.
5. EL PRIMARI PUNTO QUE IR EN CASO DE LUMBRE ES LA ESTACIONES