

EXPLANATION

CLAIMS

- WORLD'S FAIR SYNDICATE ARGENTOR GROUP OUTLINE

GEOCHEMICAL COMPOSITE

- ANOMALOUS SAMPLE LOCATION
- SILVER, ANTIMONY, ARSENIC

ALTERATION

- FRESH
- ARGILLIC
- SILICIFICATION
- CONTACT

STRUCTURE

- DIORITE
- CONGLOMERATE
- ANDESITE
- QUARTZ PHENO (TUFF?)
- RHYOLITE INTRUSIVE
- CONTACT
- FAULT
- VEIN

WORKINGS

- CONTROL POINT
- 2ND DARY POINT
- MINE DUMP OR WORKINGS
- MINE SHAFT OR PIT
- POLE
- UNDERGROUND WORKINGS (NOT SURVEYED POSITION APPROX.)
- PHOTO PANELS
- UPPER ADIT
- LOWER or MAIN TUNNEL
- FIRST LEVEL in WINZE
- SECOND LEVEL in WINZE
- THIRD LEVEL in WINZE
- FOURTH LEVEL in WINZE
- FIFTH LEVEL in WINZE

0 200' 400'
Scale Feet

FEB. 1982

MAP REV DATE
9-83 EGH

GEOLOGIC INFO FOR MAP COMPILED BY J. RICE AND P. EIMON

MULTI – COMPOSITE
OF
WORLD'S FAIR PROJECT
SANTA CRUZ COUNTY, ARIZONA
FOR
WORLD'S FAIR SYNDICATE
BY
E. GROVER HEINRICHS & ASSOCIATES
1802 W. GRANT RD., SUITE 110-4, TUCSON, AZ. 85705