

Fig. 3.- Geologic map, 152-foot level, Lake Shore Copper Deposits, Pinal County, Arizona.