U.S. DEPARTMENT OF THE INTERIOR - BUREAU OF MINES

VERTICAL SECTION ON LATITUDE SOUTH 1910, LOOKING NORTH, CERBAT MT. ZINC PROJECT NO. 1506



Notes:
Figures to right of drillholes are core sample assays.
Figures to left of drillholes are sludge sample assays.
First fig. is length of sample.
Second fig. is % Zinc.
Third fig. is % Copper.
Fourth fig. is % Lead.

VALUES CUT IN HOLE NO. 6 - JOHNNY BULL & SILVER KNIGHT CLAIMS

Scale: 1" = 50'

Dec. 7, 1943