CONTACT INFORMATION
Mining Records Curator
Arizona Geological Survey
416 W. Congress St., Suite 100
Tucson, Arizona 85701
520-770-3500
http://www.azgs.az.gov
inquiries@azgs.az.gov

The following file is part of the

Reconstruction Finance Corporation Arizona Records

ACCESS STATEMENT

These digitized collections are accessible for purposes of education and research. We have indicated what we know about copyright and rights of privacy, publicity, or trademark. Due to the nature of archival collections, we are not always able to identify this information. We are eager to hear from any rights owners, so that we may obtain accurate information. Upon request, we will remove material from public view while we address a rights issue.

CONSTRAINTS STATEMENT

The Arizona Geological Survey does not claim to control all rights for all materials in its collection. These rights include, but are not limited to: copyright, privacy rights, and cultural protection rights. The User hereby assumes all responsibility for obtaining any rights to use the material in excess of "fair use."

The Survey makes no intellectual property claims to the products created by individual authors in the manuscript collections, except when the author deeded those rights to the Survey or when those authors were employed by the State of Arizona and created intellectual products as a function of their official duties. The Survey does maintain property rights to the physical and digital representations of the works.

QUALITY STATEMENT

The Arizona Geological Survey is not responsible for the accuracy of the records, information, or opinions that may be contained in the files. The Survey collects, catalogs, and archives data on mineral properties regardless of its views of the veracity or accuracy of those data.

RECONSTRUCTION FINANCE CORPORATION

MINING DIVISION

LIQUIDATION REPORT OF SUPERVISING ENGINEER

Applicant: Carl Eder
Docket: No. B-ND-4018
Date of Report: Sept. 9, 1944

1. NAME AND ADDRESS OF APPLICANT:

Carl Eder
P. O. Box 1734
Globe, Arizona

2. LOCATION OF PROJECT:

In the Lower Pinto Valley Mining District, Gila County, Arizona, 10 miles from Miami, Arizona.

3. AMOUNT OF LOAN AND DATE OF AUTHORIZATION:

A $5000 loan was approved on September 18, 1942.

4. PURPOSES FOR WHICH LOAN WAS EXPENDED:

To develop a zinc mine by means of drifts.

5. EQUIPMENT:

Aside from a few hand tools not worth salvaging, there was no equipment purchased with loan funds. Since the mine is located about 1-1/2 miles from the nearest road the cost of reclaiming these tools would far exceed their value which I estimate at about $25.00.

6. PROPERTY:

The borrower owns the seven unpatented lode claims upon which this loan was granted.

7. COMMENTS:

Mr. Bryan Frisbie, Supervising Engineer from this office, last visited the property on June 7, 1944. During the latter part of July, 1944, the applicant ceased work on this project.

All items in this account have been liquidated and the balance in the loan account, amounting to $847.49, has been sent to the Federal Reserve Bank.

8. CONCLUSION:

The proposed project failed to develop a sufficient quantity of ore to justify further development and the property is believed to be of little value. Consequently the loan should be considered a loss.

9. RECOMMENDATION:

It is recommended that this account be closed.

WM. B. MAITLAND, Supervising Engineer

Liquidation Report

Carl Eder
BMO 4018
Sept 8, 1944

1. Name + Address of Applicant

Carl Eder
PO Box 1734
Globe, Arizona

2. Location of Project

On the Lower Pinto Valley Mining District, Gila Co, Ariz., 10 miles from Miami, Ariz.

3. Amount of ~~Loan~~ and Date of Authorization

a $5000 loan was approved on Sept 18, 1942

4. Purposes for which Loan was Expended

To develop a zinc mine by means of drifts ~~+ ~~

5. Equipment

aside from a few hand tools not worth salvaging there were no equipment purchased with loan funds. Since the mine is located about 1½ miles from the nearest road the cost of reclaiming these tools would far exceed their value which of estimate at about $25.00

6. Property

The borrower owns the seven unpatented lode claims upon which the loan was granted

7 Comments

Mr ~~F.P. Lowe~~ Burgan Jenkins, ~~Engineer~~ Engineer from this office last visited the property on ~~Aug 2, 194~~ June 7, 1944. During the latter part of June 1944 the applicant ceased work on this project

all items in this account have been liquidated and the balance in the loan account amounting to $847.49 has been sent to the Federal Reserve Bank

8 Conclusion

The proposed project failed to develop a sufficient quantity of ore to justify further development & the property is believed to be of little value. Consequently the loan should be considered a loss.

9 Recommendation

It is recommended that this account be closed.

Wm B Mumford
Sup Engr

Carl Eder = 4018
BN - Reg 1734
globe.

R. Carl Eder
Denbeigh Mo.

Dear Mr. Eder

I visited your mine Wednesday afternoon and was sorry to have missed you. One of your neighbors said he thought you were there so I would not have driven in.

I examined the workings and noted that you had carried the north tunnel to a point approximately 145 feet from the portal. I noted that the good showing of ore which I sampled in the start of the tunnel continued only a few feet and that the balance of the tunnel shows only barren or very low grade material with nothing of interest in the face. Mr. Maitland who visited the mine early in May advised discontinuing work here and transferring your operations to the south tunnel. You have advanced the north tunnel approximately 40 feet since his visit and have encountered nothing of importance and I would strongly urge therefore that you discontinue work here and begin developing in the south tunnel. ~~As per from my sampling of the property indicated the probable a presence of the 60 foot length ore in and the area indicated in the south tunnel near the short cross cut. Through ore short is indicated, though not of~~

~~at the entrance to the south tunnel~~

No 1

As you know my sampling indicated three ~~possible~~ probable shoots of ore:

No 1. At the portal of the ~~south~~ north tunnel.

No 2. ~~A sixty foot length of ore in~~ the north tunnel at the ^short^ tunnel's name

No. 3. at the portal of the south tunnel. This shoot however was not so clearly indicated as the others.

The work which you have done to date has disproved the ^the expected No. 2 ore^ presence of ~~an~~ shoot in the north tunnel. ~~My sampling of the~~ No 2 ~~ore shoot~~ in the south tunnel indicated a ^60 foot^ length of ore which will run out ^ at around 20% Sn. Material of this ~~grade material~~ could be shipped to custom mills at a good profit particularly if, as seems likely, you properly become eligible to receive additional premium prices for zinc.

I wish to ~~emphasize~~ the fact that these loans are not made for the purpose of prospecting. Our aim is get ~~the~~ metal ~~out~~ on the market as soon as possible and therefore we should develop as for

130
2600

as is practical only in the areas where ore is known to exist. Prospect development would be a later consideration.

I hope that you will appreciate the reasonableness of the above comments and will begin active development in the south tunnel as soon as possible.

I wish to compliment you upon the excellent condition of your workings and the amount of work you have done with the funds you have expended to date.

I shall look forward to seeing you upon my next visit. Meanwhile, with kindest regards, I remain

Very sincerely

T. P. Lan
Insp Eng.

Memorandum of Visit of
Supervising Engineer

Carl Eder

Docket No. B-ND-4018

On April 25, 1943 I visited the above captioned mine at the request of the applicant in order to inspect the progress to date.

On Sept 18, 1942 the R.F.C. granted a $5000 development loan on this project. This money was to be spent ~~upon~~ on the development of a zinc vein of ore located about a mile from the end of a poor road.

The applicant advanced the north drift 90 feet along the vein by using hand steel and wheelbarrows. He has spent $1.524.65 to date so has a balance of $3175.35 remaining from the loan funds. The applicant only draws miners wages when he works and has been very frugal. all work to date has been well done and no money has been wasted.

The attached map is based on the original assaying and survey of T. P. Lane, Supervising Engineer who originally examined the mine plus the new work inspected and sampled by this engineer. No new ore was exposed by this tunnel so I have recommend to the applicant that further development work be confined to vertical development on the two known ore shoots. Apparently the available ore on this property will be smaller less than originally anticipated so I have requested

the applicant to do all future work only in known ore. This work will consist of raising in the ore body south of the creek and a limited amount of drifting south along the parallel vein at Sample No 8. It would not seem feasible at this time to attempt to sink on the ore due to the fact that water from the creek would probably drown out any small pumps and the lack of a road prohibits the installation of a large pumping unit.

There is some doubt whether the sphalerite occurs as a true vein as it appears to be a magmatic segregation of zinc sulfides in an extremely basic igneous dike. I do not believe that the ore will extend to any great depth.

Wm B Mentzel
Supervising Engineer

Letter of Transmittal

Eden

N35E Strike Dip 76°S

Tunnel 45' Good HW Ragged FW

Diabase ledge in Schist

Hvy pyrite some qtz. Vry little Py

450' W from End line Reliance

Caved tunnel 40' is a straight take off southerly for main ledge.

Precis on dump shows good Cu prospect. mm qtz. Diabase rein mat. much kaolinized

100' east from end of Schist. Claim

Top of Hill is 100' E from Ant. Loc 1

cut shows Cu and qtz stain. Cut runs shallow and sloughed. Next here shows red iron stained diabase in schist

90' shaft at center of Adelaide
claim x-cut 30' to ledge
22' ledge. Said to run 3-3½ Oz
Few hundred lbs packed out
Strike S65W
shaft w/ winders, ladders out
some water on dump (Tom C + Co)
1 3 to 1 1/2 Amarock w/ 300' levels

1'gun switchdisplay
W
Fire is smooth
HGV alloy is d'aumpard is smooth



3'hike w/1'barren in middle




S37W
48 Face
S16W 30'
S25°W 70"
40' to slope
S35°W-100' wall
S48°W curving
48'

Sample #1 2 ft" Face Vy Hd FeCu
Mn qtz? smear veinlets Qtz
wall mot def. Diabase

Sample #2 25' back from face
1" Vy fld white vein w/Qtz?
in back center of drift
Wall not def.

Sample #3 Hd iron in back Mn
wall center of back 15"
Sample at ⊕ on turn
Mn 4' edge of stope



#5 - 27" 33' back from stope
Hd w/ sulf stks. Rgn S, Fus S.

#6 24" across back just in
Arm sec. Modular form
w/ nuggets sphalerite.
(1100' lin)

#7 at one 24" in



streaks Zn S.
Area lin for 30' in
is heavily fractured and
white fine clastic deposit
coats walls. Fus S
block and rosin bum
then pan and spitted for
balance except when
sampled

#8 see above sketch

#9 Dump (picked dump) 5+ tons

#10 East turned face is
ni 30' Sample 36" inch
Much Rosin Sm
Front. & much white
coat (powdery on floor
Face ~~to~~ Sid ni ~~blades~~)



Carl Eder $5000 Bloom

Balance 4/15/43 $3175.35

Eder Zn April 25, 1943

Sample No 1B - 2' Zn vein 8' east of portal of S drift + in short 8' drift face

Sample No 2B 3' face of above drift. But on W side of Sample No 1B Eder claims this is low grade - Looks like diabase only

Sample No 3B - 4½' back of N drift 10' in from face at time of Lance visit

Sample No 4B - 5' 25' in from No 3B in tunnel back

Sample No 5B - 3½' 57' in from portal

Sample No 6B - Grab from muck pile at face 90' in

CLAUDE E. McLEAN
P. O. BOX 1888

TELEPHONE 3-6272

ARIZONA TESTING LABORATORIES

ANALYTICAL AND CONSULTING CHEMISTS
ASSAYERS, MINING ENGINEERS
823 EAST VAN BUREN STREET

ASSAY CERTIFICATE

PHOENIX, ARIZONA April 28, 1943

Mr. W. B. Maitland, Supervising Eng., RFC

325 Heard Building, Phoenix, Arizona

WE HAVE ASSAYED THE SAMPLES RECEIVED FROM YOU AND FIND THE RESULTS AS FOLLOWS:

GOLD FIGURED AT $_____ PER OUNCE.

LAB. FORM 2 SILVER FIGURED AT $_____ PER OUNCE.

LAB. NO.	SAMPLE	GOLD		SILVER		PERCENTAGES		
	Carl Eder	OZ. PER TON	VALUE	OZ. PER TON	VALUE	COPPER	LEAD	Zinc
47529	#1B							7.20%
47530	#2B - 3'							0.90
47531	#3B - 4½'							4.60
47532	#4B							5.90
47533	#5B							5.60
47534	#6B Grab							0.70

REGISTERED ASSAYER
CERTIFICATE EXPIRES
CLAUDE E. McLEAN
DEC. 31, 1943
ARIZONA U.S.A.

RESPECTFULLY SUBMITTED,
ARIZONA TESTING LABORATORIES

BY Claude E. McLean
ASSAYER

CHARGES $ 6.00

Reconstruction Finance Corporation
Mining Division
Supplemental Report of Supervising Engineer

Docket No. B-ND-4018
Date of Examination, inclusive Aug 11, 1942
Date of Original Report July 27, 1942
Date of Supplemental Report

1. Name and Address Carl Eder
Address P.O. Box 1734
City and State Globe, Arizona

Note. Examination was made for the purpose of obtaining more samples to support the conclusions set forth in the original report on the property.

Mapping.

The accompanying map shows a corrected location of the tunnel in the south bank of the gulch. The vegetation is heavy in the gulch and the original bearing across the creek was obtained by sighting on an erroneous point on the hillside above the brush. The new plotting indicates that the tunnels are driven on parallel veins or faulted segments of the same vein. The latter explanation seems the more likely one since the extensions of the veins are not visible in the opposite banks. Overburden is heavy and no work has been done at these points.

Sampling

The tunnels were sampled at ten foot or closer intervals in the ore shoots.

Samples were cut across the back for the full width of the drift. The walls in the ore zones

are well defined with generally several inches of soft crushed vein material against each wall. ~~[illegible]~~ The floor of the south tunnel is generally covered with mud and water and the back and walls ~~[illegible]~~ sloughed in places, particularly in the area where the small stope has been started.

Values

A 60 foot length of continuous ore shows in the south tunnel where samples assayed as follows:

Sample No.	Width	% Sn
4	48	68.2
5	27	23.0
14	65	17.85
16	77	20.13
17	34	14.38
18	44	28.35
19	38	16.16
20	42	11.80
Weighted Ave	46.4"	25.20

The north tunnel starts as an open crosscut which upon intersecting the vein follows it and ends in 14 feet of tunnel. The crosscut and tunnel are partially filled with broken vein material; slightly chunky of good ore. Samples here over a length of 23 ft assayed as follows:

Sample No.	Width	% Sn
10	36"	28.80
11	42"	26.48
12	36"	27.72
13	36"	5.75
Weighted Ave.	37.5"	22.34

are well defined with soft crushed material against each wall. The hanging wall tends to flake and slab off in the area where the small stope has been started. The floor of the north tunnel is generally covered with mud and water and the walls and back are sloughed in places.

Values:

Sampling in the north tunnel shows a 60 foot length of continuous ore. ~~While the lens does not always fill the drift the samples were cut across the full width of the drift. Samples in the short are tabulated below,~~ with assay results as follows:

Sample No.	Width	% Zn
4	48	68.2
5	27"	23.0
14	65"	17.85
16	77"	20.13
17	34"	14.38
18	44"	28.35
19	38"	16.16
20	42"	11.80
		25.20
Weighted Ave.	46.4"	

3273.60
621.00
1140.25
1560.01
488.92
1247.40
614.08
495.60
9450.86

Sampling in the south tunnel shows a 25' length of ore. ~~The tunnel starts as an open crossant~~

The south tunnel starts as an open crossant which upon intersecting the vein follows it and ends in a 14 ft length of tunnel. The crossant and ~~part of the~~ tunnel are partially filled with broken vein material, chiefly chunks of good zinc ore. Samples ~~for~~ over a length of 23 ft. assayed as following: ~~as to~~:

Sample No	Width	% Zn
10	36"	28.80
11	42"	26.48
12	36	27.72
13	36"	5.75

22.34

1036.80
1108.80
997.92
207.00

Ten feet north of sample No. 21 the tunnel shows no ore whatever and from this point to within about 40 ft of the portal of the tunnel there is no ore showing of importance. Samples No. 7 and No. 22 indicate the presence of a short lens of ore at the portal of the tunnel the work is near the surface and the drift has broken thru and considerable surface material has run in onto the drift floor north and down sample No. 7. The north end of the vein exposure passes into surface dirt and sample No. 23 contained much dirt and foot wall material and cannot be considered truly representative of the vein at this point.

The north tunnel starts as an open cross cut which upon intersecting the vein follows it and ends in 14 feet of tunnel. The crosscut and tunnel are partially filled with broken vein material, chiefly chunks of good ore. A zone of cross fracturing occurs at the south end of this exposure but the vein does not seem to have been displaced. The vein shows for several feet south of sample No 13 and cannot be traced further because of muck dirt which is piled here and because of the overburden of the creek bank. Samples in this working place show on a vein length of 23 feet assayed as follows:

Sample	Width	% Zn.
10	36	28.80
11	42	26.48
12	36	27.72
13	36	5.75
Weighted Ave.	37.5"	22.34

The samples as noted above are taken across the full width of the drift. The ore occurs chiefly in massive form rather than in fine dissemination and

some sorting would be possible. Sampling indicates that the material in the ore shoots would run out at somewhat over 20% zinc. Samples in the north and south shoots were cut across the full width of the drifts, and since the ore occurs largely in massive form ~~sphalerite~~ ~~rock with thin~~ some sorting out of waste would be possible.

Ore Reserves

The present development on the property does not block out any ore. A vertical projection of the north shoot to the surface would, give a length of approximately 100 feet. Driving on the vein in the south tunnel will gain roughly .8 ft of backs for each foot of advance into the hill.

Proposed Development

The development program would aim at blocking out ore by raising in the south ore shoot, and driving the north tunnel to the limits of the north shoot, or, assuming that the ore continues in this force, sufficiently far to justify raising to block out ore. If the development tunnel proves that the shoot is short it would be ~~easy~~ advisable to sink either on the shoot or on the south shoot. Estimated cost for this program ~~would be about~~ is given in the original report.

Ore reserves would be stoped until the property shall have been developed sufficiently ~~reserves had been blocked out to justify building of a road in the canyon~~ down the canyon to justify building a road down the canyon.

Comments of Supervising Engineer

The possibilities for developing a small mine and an appreciable amount of zinc in a short time and at small cost seem good.

The proposed development in the south shoot could be reasonably expected to block out approximately 2000 tons for with a profit of $6.00 per ton as indicated by sampling on the level. Another shoot of profitable ore is indicated in the shoot north tunnel with good ore continuing in the face; and it is possible that a third shoot is present at the portal of the south tunnel and under the creek.

A development loan appears to be justified.


#1
54" - 2.4 %
#2
42" - 11.5 %
#3
15" - 4.2 %
#4
42" - 6.2 %
#5
27" - 23.0 %
#6
24" - 1.8 %
#7
36" - 37.2 %
12"
18.9 %





DOCKET NO. B-ND-4081

CARL EDER
PINTO VALLEY MINING DIST.
GILA CO., ARIZONA
Scale 1"=40'

T.P. Lane and Wm. B. Maitland
April 25, 1943
Assays in % Zinc

Sample No.	Width	%Zn.
1	24"	2.40
2	12"	11.50
3	15"	4.30
15	60"	5.75
14	65"	17.85
4	48"	68.20
16	77"	20.13
17	34"	14.38
18	44"	28.35
19	38"	16.16
20	42"	11.80
5	27"	23.00
21	38"	4.46



Sample No.	Width	% Zn
22	30"	17.36
7	26"	37.20
23	36"	3.07
8	12"	18.90
10	36"	28.80
11	42"	26.48
12	36"	27.72
13	36"	5.75



DOCKET NO. B-ND-4081.3

EDER GROUP
PINTO VALLEY MINING DIST.
Gila Co., Arizona
Scale: 1" = 40'

Ore
Proposed Work

T. P. Rowe
8/23/43