



**LEGEND**

- ☐ Top of Raise (Rs.) or Winze (Wz.)
- ☐ Bottom of Raise or Winze
- ▨ Winze with ladder
- ▨ Raise with ladder
- Stope Outline
- Underground Survey Station, (Level and station and Number.)
- Surface Survey Station and Number.
- ch. Ore Chute



COLEMAN EXPLORATION & MINING CO.  
**COLUMBIA - SILVER BELL MINE**  
**ORE RESERVE MAP**  
**No. 3 ADIT LV. (3130)**  
 Pioneer Mining District  
 Pinal County, Arizona

SCALE: 1" = 30 FT.  
 0 5 10 15 20 25 30 40 50 60 70 80 90 100  
 JAN., 1980