


**LEGEND**

- ☒ Top of Raise (Rs.) or Winze (Wz.)
- ☒ Bottom of Raise or Winze.
- ▬ Winze with ladder.
- ▬ Raise with ladder.
- ⋯⋯ Slope Outline.
- 3-8 Underground Survey Station, (Level and station and Number.)
- 3-2+ Surface Survey Station and Number.
- Ch. Ore Chute.
- 6.675 Coleman Samples - footage & Silver content.
- 9.16 Starbird Samples - Silver content only.



COLUMBIA - SILVER BELL MINE  
**SAMPLE ASSAY MAP**  
 4<sup>th</sup> LEVEL (3070)  
 Pioneer Mining District  
 Pinal County, Arizona  
 SCALE: 1" = 30 FT.  
 JAN, 1980