


SE. 65° NW.



NOTE

This Map has been traced from an old print dated October 31, 1942. From what little the writer observed while underground there are several errors in the underground workings as shown-- principally, the raking position of Shaft No. 2. The writer descended this shaft to the 60 foot level. In that distance the Shaft did not have a rake as shown. It is not known what the map preparer had in mind. The Shaft is at an angle of -50 to 55°.

This old print does show where 62 car shipments were mined (not included on this Map). In place of the car number, the writer has substituted the Silver content of the shipment. This is the important information for the moment.

This Map also shows the approximate position of the two samples (#1394 and #1395) taken by the writer on September 14, 1976.

MAP OF UNDERGROUND WORKINGS
(In Plane of Structure)
BRICK MINE
Oro Blanco Mining District
Santa Cruz County, Arizona
SCALE: 1" = 20 Feet
Sept., 1976
R.E. Mieritz
MAP N°

ADM MR 0120-006