

MINERAL HILL
INCLINE

Repeax elevation station 7007
2800.3'


700 evidence of east-west movement in a
700 horizontal plane throughout crosscut. full timbered
700 from sta. 704 to fault contact
700

work up 25' in granite
to a fault string S22E
dip 30° SW



LEGEND

- GRANITE
- LIMESTONE
- GARNETITE
- FAULT
- SULPHIDE MINER.
- GRANITE SEDIMENT CONTACT



Docet No DMEA 269-X-A
Final revision 4-17-53

FIGURE 6.
BANNER MINING CO.
MINERAL HILL MINE
700 LEVEL
GEOLOGIC PLAN

SCALE 1 IN. = 20 FT. 1-7-53

Geology by B.W. Venable
Control - Brunten - tape traverse

area within inner broken line 1312 sq. ft.
Average 2.47% Cu
 $\frac{1312}{10.5} = 129$ tons per vert. ft.

700 No. 1