

CONTACT INFORMATION

Mining Records Curator Arizona Geological Survey 1520 West Adams St. Phoenix, AZ 85007 602-771-1601 http://www.azgs.az.gov inquiries@azgs.az.gov

The following file is part of the

Arizona Department of Mines and Mineral Resources Mining Collection

ACCESS STATEMENT

These digitized collections are accessible for purposes of education and research. We have indicated what we know about copyright and rights of privacy, publicity, or trademark. Due to the nature of archival collections, we are not always able to identify this information. We are eager to hear from any rights owners, so that we may obtain accurate information. Upon request, we will remove material from public view while we address a rights issue.

CONSTRAINTS STATEMENT

The Arizona Geological Survey does not claim to control all rights for all materials in its collection. These rights include, but are not limited to: copyright, privacy rights, and cultural protection rights. The User hereby assumes all responsibility for obtaining any rights to use the material in excess of "fair use."

The Survey makes no intellectual property claims to the products created by individual authors in the manuscript collections, except when the author deeded those rights to the Survey or when those authors were employed by the State of Arizona and created intellectual products as a function of their official duties. The Survey does maintain property rights to the physical and digital representations of the works.

QUALITY STATEMENT

The Arizona Geological Survey is not responsible for the accuracy of the records, information, or opinions that may be contained in the files. The Survey collects, catalogs, and archives data on mineral properties regardless of its views of the veracity or accuracy of those data.

PRINTED: 08/16/2002

ARIZONA DEPARTMENT OF MINES AND MINERAL RESOURCES AZMILS DATA

PRIMARY NAME: SUMMIT MINE

ALTERNATE NAMES:

PIMA COUNTY MILS NUMBER: 427

LOCATION: TOWNSHIP 19 S RANGE 15 E SECTION 22 QUARTER S2 LATITUDE: N 31DEG 45MIN 42SEC LONGITUDE: W 110DEG 47MIN 50SEC

TOPO MAP NAME: SAHUARITA - 15 MIN

CURRENT STATUS: UNKNOWN

COMMODITY:

LEAD COPPER

BIBLIOGRAPHY:

AZBM FILE DATA ADMMR SUMMIT MINE FILE USGS BULL 582, P 156

LEPARTMENT OF MINERAL RESOURCES

OWNERS MINE REPORT

Date November 20, 1939

1. Mine Summit

2. Mining District & County Greaterville, Pima Co.

4. Location 21 miles W. from Stove

3. Former name Same

5. Owner Roy Frayo

7. Operator Same

9. President No Corp.

11. Mine Supt.

13. Principal Metals Silver and Gold

15. Production Rate Not established

17. Power: Amt. & Type None

18. Operations: Present Idle

6. Address (Owner) Greaterville

8. Address (Operator)

10. Gen. Mgr.

12. Mill Supt.

14 Man Employee

SUMMIT MINE

Ag, Au

Pima

10 - 6

S 27, R 19 S, R 15 E

Roy Frajjo

19. Operations Planned Depend on financing

20. Number Claims, Title, etc. One - unpatented lode on Coronado Forest.

21. Description: Topography & Geography On Juniper Flats, on east slope hill rising 400-500 ft. above canyon. Outcrop near top.

22. Mine Workings: Amt. & Condition 1 shaft incline at 35' - 40 ft. deep,

23. Geology & Mineralization streaks 20			Pay
	er or the standard region		
(
24. Ore: Positive & Probable, Ore Dumps, Tailings	About 2 tons on dump. cut across vein.	Assay of char	nel
and the second	и (·	re. hosk
		. v	
24-A Vein Width, Length, Value, etc.		9	4
24-11 Velli Width, Eength, Valde, etc.			· · · · · · · · · · · · · · · · · · ·
			·
			" Same of the
25. Mine, Mill Equipment & Flow Sheet None			
	F	ا معارفها مرابع	in V
26. Road Conditions, Route Truck road to	property. Hauling.	g ⁶ a constant	ore, and a residue of the
20. Road Conditions, Road 17 17 17 17 17 17 17 17 17 17 17 17 17	broberch. prarring.	gran and a second	· · · · · · · · · · · · · · · · · · ·
			The state of the s
		* *	
27. Water Supply Can be developed. Now	hauling 1 mile.		
			1. 1. 1. 5 TH 1 I
28. Brief History Was worked previously		4	9. J. T.
29. Special Problems, Reports Filed See U. S.	G. S. Bull. #582- P. 15	56.	i teatro est
500 0. 5.	de De Dazze // Don- 2 e ze		
30. Remarks		era e el	
		100	
31. If property for sale: Price, terms and address to	negotiate. For sale or l	ease on reason	able terms.
Φ	oy Frayo.		
32. Signed R	of rraios		

33. Use additional sheets if necessary.

LEPARTMENT OF MINERAL RESOURCES STATE OF ARIZONA

OWNERS MINE REPORT

SEP 19 1940

ACHONA

Б.

November 19051113,59.

Mine Summit

District Greaterville, Pima Co.

Location 22 miles W. from Stove.

Former name Same

Owner Roy Fraijo

Address Greaterville

Operator Same

Address

President No Corp.

Gen. Mgr.

Mine Supt.

Mill Supt.

Principal Metals Silver and Gold

Men Employed

Production Rate Not established

Mill: Type & Cap.

Power: Amt. & Type None

Operations: Present

Idle

Operations Planned Depend on financing

Number Claims, Title, etc. One- unpatented lode on Coronado Forest.

Description: Topog. & Geog.

On Juniper Flats, on east slope hill rising 400-500 ft. above canyon. Outcrop near top.

Mine Workings: Amt. & Condition

l shaft incl. at 35'-40 ft. deep.

Ore: Positive & Probable, Ore Dumps, Tailings

About 2 tons on dump. Assay of channel cut across vein.

Mine, Mill Equipment & Flow Sheet None,

Road Conditions, Route Truck road to property. Hauling.

Water Supply Can be developed. Now hauling 1 mile.

Brief History Was worked previously.

Special Problems, Reports Filed See U. S. G. S. Bull. #582- P. 156.

Remarks

If property for sale: Price, terms and address to negotiate. For sale or lease on reasonable terms.

ម្នាស់ប្រាស់ស្រុកស្រី (សេសី) ដែលសេស ស្រាស់។ កាសលើការពេល នេះ

ager, other end or o've file de dramar - er

Signed Roy Frayo.

Mr. Roy Frayo

Arizona

Principal Left in Address

Principal Left in Add SOURCES nnds

Greaterville,

ARIZONA DEPARTMENT OF MINERAL RESOURCES MINERAL BUILDING, FAIRGROUNDS PHOENIX, ARIZONA

August 7, 1958

To the Owner or Operator of the Arizona Mining Property named below:

Summit Mine (Pima County)	silver and gold
(Property)	(ore)

We have an old listing of the above property which we would like to have brought up to date.

Please fill out the enclosed Mine Owner's Report form with as complete detail as possible and attach copies of reports, maps, assay returns, shipment returns or other data which you have not sent us before and which might interest a prospective buyer in looking at the property.

FRANK P. Knight

FRANK P. KNIGHT, Director.

Enc: Mine Owner's Report

See USSS Bull 582 p 156