



CONTACT INFORMATION

Mining Records Curator
Arizona Geological Survey
1520 West Adams St.
Phoenix, AZ 85007
602-771-1601
<http://www.azgs.az.gov>
inquiries@azgs.az.gov

The following file is part of the

Arizona Department of Mines and Mineral Resources Mining Collection

ACCESS STATEMENT

These digitized collections are accessible for purposes of education and research. We have indicated what we know about copyright and rights of privacy, publicity, or trademark. Due to the nature of archival collections, we are not always able to identify this information. We are eager to hear from any rights owners, so that we may obtain accurate information. Upon request, we will remove material from public view while we address a rights issue.

CONSTRAINTS STATEMENT

The Arizona Geological Survey does not claim to control all rights for all materials in its collection. These rights include, but are not limited to: copyright, privacy rights, and cultural protection rights. The User hereby assumes all responsibility for obtaining any rights to use the material in excess of "fair use."

The Survey makes no intellectual property claims to the products created by individual authors in the manuscript collections, except when the author deeded those rights to the Survey or when those authors were employed by the State of Arizona and created intellectual products as a function of their official duties. The Survey does maintain property rights to the physical and digital representations of the works.

QUALITY STATEMENT

The Arizona Geological Survey is not responsible for the accuracy of the records, information, or opinions that may be contained in the files. The Survey collects, catalogs, and archives data on mineral properties regardless of its views of the veracity or accuracy of those data.

PRINTED: 12/18/2002

ARIZONA DEPARTMENT OF MINES AND MINERAL RESOURCES AZMILS DATA

PRIMARY NAME: CAREY PROPERTY

ALTERNATE NAMES:

YAVAPAI COUNTY MILS NUMBER: 1073C

LOCATION: TOWNSHIP 13 N RANGE 1 W SECTION 36 QUARTER SE
LATITUDE: N 34DEG 27MIN 36SEC LONGITUDE: W 112DEG 18MIN 42SEC
TOPO MAP NAME: POLAND JUNCTION - 7.5 MIN

CURRENT STATUS: EXP PROSPECT

COMMODITY:
COPPER
GOLD
SILVER

BIBLIOGRAPHY:
ADMMR CAREY PROPERTY FILE

Intra-Company Correspondence

Carey Property

SHATTUCK DENN MINING CORPORATION
and
SUBSIDIARIES

Engineering/Geology Office

Date..... January 21, 1963

TO: D. M. Kentro

SUBJECT: Copper vein prospect near Poland
Junction, Yavapai County, Arizona.
Mr. Lesher "Slim" Carey
Dewey, Arizona

On January 4, 1963, Mr. Carey brought an ore specimen from his prospect to the Iron King Mine for our inspection. This specimen carried 0.18 oz. Au, 20.3 oz. Ag, and 27.8 % Cu/ton.

On January 8, 1963, I examined this property with Mr. Carey. The workings consist of one 30' shaft located (approximately) in the SE $\frac{1}{4}$ of sec. 36, T. 13 N., R. 1 W.--some 3.0 miles from Poland Junction, Arizona.

The property comprises one unpatented claim, and the 30' shaft. Mineralization is localized in a fault in preCambrian quartz diorite--locally some chalcopyrite is visible. The vein zone (fault) varies in thickness from nil to 1.9' at its widest point. The fault strikes N 57 E and dips 78 degrees east as observed in the shaft. The vein has pinched out at the bottom of the shaft.

Six samples were cut at three levels in the shaft. The assay results are recorded below:

SHATTUCK DENN MINING CORPORATION
and
SUBSIDIARIES

Engineering/Geology Office

Date: January 21, 1963

TO: D. M. Kentro

SUBJECT: Copper vein prospect near Poland Junction, Yavapai County, Arizona.
Mr. Leshar "Slim" Carey
Dewey, Arizona

On January 4, 1963, Mr. Carey brought an ore specimen from his prospect to the Iron King Mine for our inspection. This specimen carried 0.18 oz. Au, 20.3 oz. Ag, and 27.8 % Cu/ton.

On January 8, 1963, I examined this property with Mr. Carey. The workings consist of one 30' shaft located (approximately) in the SE $\frac{1}{4}$ of sec. 36, T. 13 N., R. 1 W.--some 3.0 miles from Poland Junction, Arizona.

The property comprises one unpatented claim, and the 30' shaft. Mineralization is localized in a fault in preCambrian quartz diorite--locally some chalcopryrite is visible. The vein zone (fault) varies in thickness from nil to 1.9' at its widest point. The fault strikes N 57 E and dips 78 degrees east as observed in the shaft. The vein has pinched out at the bottom of the shaft.

Six samples were cut at three levels in the shaft. The assay results are recorded below:

Sample No.	Width	Level	Wall	Au	Ag	Pb	Zn	Cu
# 5157	0.7'	14.0'	SW	0.06	0.40	nil	nil	1.22
# 5156	1.0'	14.0'	NW	0.02	1.80	nil	nil	2.14
# 5155	1.3'	20.0'	NW	0.01	nil	nil	nil	0.08
# 5154	1.9'	20.0'	SW	nil	nil	nil	nil	0.09
# 5153	0.9'	27.0'	SW	nil	nil	nil	nil	0.10
# 5152	0.4'	27.0'	NW	0.06	0.20	nil	nil	1.28

Samples # 5156-57 correspond to the specimen mentioned in the first paragraph.

The weighted result of these assays are: Average width of the vein is 1.1' carrying 0.016 oz. Au, 0.36 oz. Ag, and 0.6% Cu/ton.

Because of the narrowness of vein, low grade of metals therein, and apparent pinching with depth it is recommended our company show no further interest in this property.

Robert G. Raabe
Robert G. Raabe
Geologist