



- Mound Of Stone Or Test Hole Found
- Location Notice Found
- 2x2x5' Post Set In Mound Of Stone
- ⊠ 2x2x5' Post Set In Mound Of Stone With Location Notice Inside Aluminum Can Covering Top Of Post
- ⊙ Control Point - Nail And Lath
- △ Triangulation Station
- ⊗ A-4 = 8" Cased Drill Hole (Indications Of Water In Hole, Depth Of Water And Amount Not Known)

NOTES: 1. THE SURVEY AS REPRESENTED HEREON WAS DONE USING THE TRANSIT-STADIA METHOD, THE ACCURACY MUST BE CONSIDERED WHEN USING INFORMATION TAKEN FROM THIS PLAN.  
 2. ALL INFORMATION SHOWN ON THIS PLAN AND ACCOMPANYING FIELD NOTES IS THE PROPERTY OF ESSEX INTERNATIONAL, INC., AND CANNOT BE USED WITHOUT THEIR WRITTEN CONSENT.  
 3. THE LOCATION OF FLATTOP #33 COULD NOT BE DETERMINED, NO LOCATION NOTICE OR MONUMENTS THAT COULD BE IDENTIFIED AS BEING THOSE OF SAID FLATTOP #33 COULD BE FOUND.

SURVEYED UNDER MY DIRECTION DURING AUGUST-OCTOBER, 1971.



PLAN OF TRANSIT-STADIA SURVEY OF FLATTOP GROUP OF MINING CLAIMS IN SECTIONS 2, 3, 10 & 11 TOWNSHIP 6 SOUTH, RANGE 26 EAST, G & S.R.M., GRAHAM COUNTY, ARIZONA

SURVEYED AT THE REQUEST OF ESSEX INTERNATIONAL, INC., TUSCON, ARIZONA BY

ANDERSON-HERMON SAFFORD, ARIZONA