


Sample No.	Width Ft.	Oz. Ag.	Remarks
101	11	8.4	Pillar wall - stope
102	10	14.8	Above #102
103	14	18.2	Stope wall
104	8.5	12.4	Above #103
105	36	7.6	stope wall
106	Dump	4.4	At stope entrances
107	17	6.4	Stope wall
109	10	10.6	stope wall
111	7	10.8	End Stope
112	12.5	3.6	Car. Stope
113	9.5	3.4	✓ ✓
114	19	9.2	Face at stope ent.
115	17	6.0	car. stope
116	18	16.8	✓ ✓

Sample No.	Width Ft.	Oz. Ag.	Remarks
117	Dump	2.6	Cap Rock
1001	14	12.2	Face of Quarry
1002	22	3.8	✓ ✓ ✓
1003	8	.7	✓ ✓ ✓
1004	10	10.8	✓ ✓ ✓
121	15.5	8.6	✓ ✓ ✓
122	7	3.0	✓ ✓ ✓
123	18	3.8	Cut above So. Stope
124	11	11.20	Reef near creek
125	12	7.8	Face outside So. Stope
126	7.5	9.6	North cut
127	7	16.2	Pit floor No. Stope
128	Dump	5.8	Quarry Reject

— horizontal sample
 x vertical sample



SALVADOR MINE

Santa Cruz Co, Ariz.
 scale: 1" = 20'

Dec. 1, 1949

T. P. Lane

