



PROPOSED WORK

----- 905 level

===== 1158 level

..... level to be determined

⓪ & ⓫ to be determined

Fig. 8

DEPARTMENT of INTERIOR

BUREAU of MINES

905 LEVEL

Christmas Mine, Christmas, Arizona

March 6, 1951

Scale 1"=100'